EPSON Knowledge Base

Article: KB020086

Why, when using the Stylus RIP Version 4.40 with Mac OS 9.1 do I keep getting system errors and problems?

Epson Stylus RIP Version 4.40 does not function in Raster Spool Mode with Mac OS 9.1. Disable Raster Spool Mode and you should not have any further issues.

Article: KB020086 Language: English Product Range: Ink Jet Page: 1 of 1