EPSON

Knowledge Base

Article: KB020192

Why a vertical line is printed at the left side of paper on my Linux system?

This problem is caused by a rendering program of CUPS. Therefore, the problem is not avoidable. We have confirmed that the problem occurs in 1.1.14 version of CUPS.

Article: KB020192 Language: English Product Range: Dot Matrix Page: 1 of 1